

TEST REPORT

Number: GZHT02329497

Applicant: MOSAROMA INTERTNATIONAL CO.,LTD
7F, BLISSFUL BUILDING, 243-247
DES VOEUX ROAD, CENTRAL
HONG KONG
Attn: 施先生

Date: Aug 31, 2020

Sample Description As Declared :

No. Of Sample : One
Fibre Content : -
Material : 100% SOLUTION-DYED BLEND SPUN (AXVISION)
Finishing : -
End Uses : Cushion, Pillow
Season : -
Colour : Orange
Style No. : 13745762
Order No./PO No. : -
Buyer's Name : -
Manufacturer's Name : -
Ref. : -

Applicant's Provided Care Instruction/Label :

-

Date Received/Date Test Started : Aug 20, 2020

Date Final Information Confirmed: -

Prepared And Checked By:
For Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch



Lin Lin
General Manager

hyt / wenhuang



Page 1 Of 4

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch

3/F, Hengyun Building, 235 Kaifa Ave., Guangzhou
Economic & Technological Development District, Guangzhou, China
深圳天祥质量技术服务有限公司广州开发区分公司
中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼
Tel: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode:510730
www.intertek.com

Conclusion:

Based Upon The Results Of The Flammability Test Reported, The Sample Submitted For Testing Meets The Performance Requirements Of California Technical Bulletin 117-2013, Section 1, Cover Fabric Test.

Prepared And Checked By:
For Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch



Lin Lin
General Manager

hyt / wenhuang



TEST REPORT

Number: GZHT02329497

Tests Conducted (As Requested By The Applicant)

1 Flammability Test (California Technical Bulletin 117-2013 Section 1: Cover Fabric Test):

Test Method

The apparatus and method of testing were those described in California Technical Bulletin 117-2013, Section 1, for measuring the tendency of upholstery cover fabrics to smolder and contribute to fire propagation, when subjected to a smoldering ignition source.

Pass/Fail Criteria

A cover fabric material is considered pass or fail based on following criteria:

1. A single mock-up test specimen fails to meet the requirements of this test procedure if any of the following criteria occurs:
 - a) The mock-up test specimen continues to smolder after the 45 minutes test duration.
 - b) A vertical char length (measured as specified in step 11.9 of ASTM E1353-08a ^{ε1}) of more than 1.8 inches (45 mm) develops on the cover fabric.
 - c) The mock-up test specimen transitions to open flaming.
 2. The cover fabric passes the test if three initial mock-up specimens pass the test, i.e., the cigarettes burn their full length and the mock-ups are no longer smoldering.
 3. If more than one initial specimen fails, the cover fabric fails the test.
 4. If any one of the three initial specimens fails, repeat the test on additional three specimens.
 5. If all three additional specimens pass the test, the cover fabric passes the test. If any one of the additional three specimens fails, the cover fabric fails the test.
-
-

hyt / wenhuang

Page 3 Of 4

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch

3/F, Hengyun Building, 235 Kaifa Ave., Guangzhou

Economic & Technological Development District, Guangzhou, China

深圳天祥质量技术服务有限公司广州开发区分公司

中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼

Tel: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode: 510730

www.intertek.com

TEST REPORT

Number: GZHT02329497

Tests Conducted (As Requested By The Applicant)

Test Result

Initial Test				
	Vertical Char length (Inches)	Mock-up specimen continues to smolder After 45 Minutes	Mock-up test specimen transitions to open flaming	Test Result
Specimen 1	0.5	No	No	Pass
Specimen 2	0.4	No	No	Pass
Specimen 3	0.5	No	No	Pass

Conditioning : At least 24 hours in an atmosphere having a temperature of 21° ± 3 °C (70° ± 5 °F) and less than 55% relative humidity

Remark : No = Was not observed

End of Report

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct. No copy of the test report(except for full text copy) shall be made without the written approval by Intertek.

hyt / wenhuang

Page 4 Of 4

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch

3/F, Hengyun Building, 235 Kaifa Ave., Guangzhou

Economic & Technological Development District, Guangzhou, China

深圳天祥质量技术服务有限公司广州开发区分公司

中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼

Tel: +86 20 8396 6868 Fax: +86 20 8222 8169 Postcode:510730

www.intertek.com