



Intertek Testing Services Shenzhen Ltd, Guangzhou Branch

Room 401/501/601/801/901/1003, No. 8, East Baoying Road, Huangpu District
Guangzhou, China

深圳天祥质量技术服务有限公司广州分公司

广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房

Tel: +86 20 2820 9118 E-mail: sz@intertek.com Postcode: 510730
www.intertek.com

Test Report

Applicant : MOSAROMA INTERTNATIONAL CO.,LTD
7F, BLISSFUL BUILDING, 243-247
DES VOEUX ROAD, CENTRAL
HONG KONG

Issue Date : Oct 08, 2024

Attn : 施先生

SAMPLE DESCRIPTION AS DECLARED

No. of Sample	One
Fibre Content	100% Polyester
Material	Woven Fabric
Finishing	-
End Uses	OUTDOOR CUSHION/PILLOW/UP HOLSTERY
Season	-
Colour	Blue-White Stripe
Style No.	15225102
Order No./PO No.	-
Standard	-
Buyer's Name	-
Manufacturer's Name	-
Ref	Sample Name: 100% Solution- Dyed Polyester SDP(AXVISION)
Date Received/Date Test Started	Sep 27, 2024
Confirmation Date	-

Intertek Testing Services Shenzhen Ltd, Guangzhou Branch

Room 401/501/601/801/901/1003, No. 8, East Baoying Road, Huangpu District
Guangzhou, China

深圳天祥质量技术服务有限公司广州分公司

广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房

Tel: +86 20 2820 9118 E-mail: sz@intertek.com Postcode: 510730
www.intertek.com

Conclusions

Test Item

Flammability Test (Cover Fabric Test)

P1

Note:

Tests presented in this report are conducted as requested by Applicant.

P = Pass F = Fail # = No Comment C = Conform Label

N/A = Not Applicable - = Did Not Perform * = See Remark

Remark:

P1 Based Upon The Results Of The Flammability Test Reported, The Sample Submitted For Testing Meets The Performance Requirements Of California Technical Bulletin 117-2013, Section 1, Cover Fabric Test.

Approved By:

Intertek Testing Services Shenzhen Ltd,
Guangzhou Branch



James Ma

Textile Lab Senior Manager

Reviewer: Jiahui Shen

Intertek Testing Services Shenzhen Ltd, Guangzhou Branch

Room 401/501/601/801/901/1003, No. 8, East Baoying Road, Huangpu District
Guangzhou, China

深圳天祥质量技术服务有限公司广州分公司

广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房

Tel: +86 20 2820 9118 E-mail: gz@intertek.com Postcode: 510730
www.intertek.com

1 Flammability Test (Cover Fabric Test)

California Technical Bulletin 117-2013 Section 1

Test Method

The Apparatus And Method Of Testing Were Those Described In California Technical Bulletin 117-2013, Section 1, For Measuring The Tendency Of Upholstery Cover Fabrics To Smolder And Contribute To Fire Propagation, When Subjected To A Smoldering Ignition Source.

Test Condition

Preconditioning: At Least 24 Hours In An Atmosphere Having A Temperature Of $21\pm 3^{\circ}\text{C}$ ($70\pm 5^{\circ}\text{F}$) And Less Than 55% Relative Humidity

	Result		
	Specimen 1	Specimen 2	Specimen 3
Vertical Char Length	0.9 in	1.0 in	1.0 in
Mock-Up Specimen Continues To Smolder After 45 Minutes	No	No	No
Mock-Up Test Specimen Transitions To Open Flaming	No	No	No

Remarks:

No = Was Not Observed

Pass/Fail Criteria

A Cover Fabric Material Is Considered Pass Or Fail Based On Following Criteria:

- A Single Mock-up Test Specimen Fails To Meet The Requirements Of This Test Procedure If Any Of The Following Criteria Occurs:
 - The Mock-up Test Specimen Continues To Smolder After The 45 Minutes Test Duration.
 - A Vertical Char Length (Measured As Specified In Step 11.9 Of ASTM E1353-08a ^{£1}) Of More Than 1.8 inches (45 mm) Develops On The Cover Fabric.
 - The Mock-up Test Specimen Transitions To Open Flaming.
- The Cover Fabric Passes The Test If Three Initial Mock-up Specimens Pass The Test, I.E., The Cigarettes Burn Their Full Length And The Mock-ups Are No Longer Smoldering.
- If More Than One Initial Specimen Fails, The Cover Fabric Fails The Test.
- If Any One Of The Three Initial Specimens Fails, Repeat The Test On Additional Three Specimens.
- If All Three Additional Specimens Pass The Test, The Cover Fabric Passes The Test. If Any One Of The Additional Three Specimens Fails, The Cover Fabric Fails The Test.

Intertek Testing Services Shenzhen Ltd, Guangzhou Branch

Room 401/501/601/801/901/1003, No. 8, East Bao'ing Road, Huangpu District

Guangzhou, China

深圳天祥质量技术服务有限公司广州分公司

广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房

Tel: +86 20 2820 9118 E-mail: info@intertek.com Postcode: 510730

www.intertek.com

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.

Intertek Testing Services Shenzhen Ltd, Guangzhou Branch

Room 401/501/601/801/901/1003, No. 8, East Baoying Road, Huangpu District
Guangzhou, China

深圳天祥质量技术服务有限公司广州分公司

广州市黄埔区保盈东路8号401房、501房、601房、801房、901房、1003房

Tel: +86 20 2820 9118 E-mail: sz@intertek.com Postcode: 510730
www.intertek.com